



Copyright

© 2015, FLIR Systems, Inc.

All rights reserved worldwide. Names and marks appearing herein are either registered trademarks or trademarks of FLIR Systems and/or its subsidiaries. All other trademarks, trade names or company names referenced herein are used for identification only and are the property of their respective owners.

Document identity

Publ. No.: LX400052
Commit: 22570
Head: 22570
Language: en-US
Modified: 2015-01-15
Formatted: 2015-01-15

Website

www.flirsecurity.com/pro

Technical Support

1-866-816-5919

Customer Service

1-866-344-4674

Legal disclaimer

Specifications subject to change without further notice. Camera models and accessories subject to regional market considerations. License procedures may apply. Products described herein may be subject to US Export Regulations. Please refer to exportquestions@flir.com with any questions.

1 DNR400 / DNR500 Series Firmware Upgrade Release Notes


1.1 January 15, 2015

Firmware version 00013 is a new firmware version for the DNR400 and DNR500 Series.

This firmware provides the following system enhancements:

- Improved FLIR Cloud connectivity when viewing on mobile devices.
- Fixed rebooting issue when using multiple high capacity hard drives.

The NVR will automatically detect and install the firmware upgrade if it is connected to the Internet. The upgrade may take between 5–10 minutes.

 CAUTION
DO NOT unplug the power cable, turn off the NVR, or disconnect the Ethernet cable until the firmware upgrade is complete. Firmware upgrade is complete when the NVR returns to the split-screen view.